

CERTIFICATE OF ACCREDITATION

This is to attest that

MCNAMARA/SALVIA OF NEW YORK P.C.

45 WEST 45TH STREET 17TH FLOOR (PH) NEW YORK, NEW YORK 10036, U.S.A.

Special Inspection Agency SIA-306-NY (Type A)

has met the requirements of the applicable provisions of AC291, IAS Accreditation Criteria for Special Inspection Agencies, and has demonstrated compliance with ISO/IEC Standard 17020:2012, Conformity assessment - Requirements for the operation of various types of bodies performing inspection, Rules of City of New York, 1RCNY 101-06, and applicable New York City Building Code® Chapter 17, Section BC 1705. This organization is accredited to provide the services specified in the scope of accreditation.

Valid thru March 1, 2026 Effective Date February 5, 2024



International Accreditation Service
Issued under the authority of IAS management

SCOPE OF ACCREDITATION

International Accreditation Service, Inc.
3060 Saturn Street, Suite 100, Brea, California 92821, U.S.A. | www.iasonline.org

MCNAMARA/SALVIA OF NEW YORK P.C.

www.mcsal.com

Contact Name Vladimir E. Seijas Contact Name Juan D. Restrepo **Contact Phone** +1-212-246-9800

Accredited to ISO/IEC 17020:2012

Effective Date February 5, 2024

Section 5 of IAS AC291 is replaced by Rules of City of New York, 1RCNY 101-06, Appendix A and applicable New York City Building Code® Chapter 17, Section BC 1704.

Field and Types of Inspection		Inspection Procedures and Reference Documents	
Management System Documentation: Special Inspections Quality Manual (SIQM), Rev.7 1/20/23 for applicable NYC Construction Codes and 1RCNY 101-06, Rules of the City of New York			
2014 Code Special Inspection	2014 Code Section	Corresponding 2022 Code Special Inspection	Corresponding 2022 Code Section
Structural Materials & Construction Operations			
Concrete - Cast-in-Place	BC 1704.4	Concrete - Cast-in-Place	BC 1705.3
Concrete - Prestressed	BC 1704.4	Concrete - Prestressed	BC 1705.3
Concrete - Precast	BC 1704.4	Concrete - Precast	BC 1705.3
Masonry	BC 1704.5	Masonry	BC 1705.4
Post-installed anchors	BC 1704.32	Post-installed anchors	BC 1705.37

