



International Accreditation Service, Inc.
3060 Saturn Street, Suite 100
Brea, CA 92821 USA
t: 562.699.4522
t: 866.427.4422
f: 562.699.8031
www.iasonline.org

Training Program for UNCERTAINTY IN MEASUREMENT

PROGRAM SCHEDULE

(All times are approximate and are subject to change based on daily progress)

DAY 1

8:00 AM	Welcome/ Pick up course materials/ Sign-In
8:30 AM - 10:30 AM	Introduction to Measurements and Dimensional Metrology
11:00 AM - 11:30 AM	Coffee/Tea Break
11:30 AM - 1:00 PM	Fundamentals of Testing and Calibration
1:00 PM - 2:00 PM	Lunch Break
2:00 PM - 3:30 PM	Calibration and Traceability Concepts
3:30 PM - 4:00 PM	Coffee/Tea Break
4:00 PM - 4:45 PM	Care in Calibration and Methodologies of Calibration
4:45 PM - 5:00 PM	Interactive Session

DAY 2

8:00 AM - 8:30 AM	Review of 1 st Day and Q&A
8:30 AM - 10:30 AM	Concept of Measurement Uncertainty
10:30 AM - 11:00 AM	Coffee/Tea Break
11:00 AM - 1:00 PM	Measurement Uncertainty and its Evaluation and Case Studies
1:00 PM - 2:00 PM	Lunch Break
Afternoon Session	Exam, Q&A and Wrap-up